


Quick-Key Combinations



	Speed Power P1 3 s	Setter/ Direct Link Power P2 3 s	USB Power P3 3 s	System Configuration Power P4 3 s
P1	+100	Direct Link	Software Update	CPO
P2	+10	+10		PBO
P3	+1	+1		Metric Units
P4	Read	Read	Save logs to USB	US Units

Program Copy	
	Power P4 3 s
Power P1 3 s	Copy Program 1 setting to all programs
Power P2 3 s	Copy Program 2 setting to all programs
Power P3 3 s	Copy Program 3 setting to all programs
Power P4 3 s	Copy Program 4 setting to all programs

Default Program Values

Program	Prebake (CPO)				Postbake (PBO)			
	cm/min	in/min	C	F	cm/min	in/min	C	F
P1	85	33	140	284	85	33	250	482
P2	91	36	140	284	91	36	250	482
P3	110	43	140	284	110	43	250	482
P4	130	51	140	284	130	51	250	482